
Chemicals in Lab Sump			
Hydrocarbo	on Reagents		
1,2-dichloroethane-d4	Isopropanol		
1,4-dichlorobenzene-d4	Isopropyl benzene		
2-Propanol	Methanol		
4-bromoflourobenzene	methyl ethyl ketone		
5-choloro-tricholoromethyl pyridine	methyl isobutyl ketone		
80% iso-oct/20% n heptanes	Mineral Oil		
acetone	MTBE		
acetonitrile	naphthalene		
Benzene	n-butanol		
BOD Nutrient buffer	n-butyl benzene		
chlorobenzene-d5	n-decane		
cyclohexane	n-heptane		
cyclopentane	n-nonane		
ETBE	neo hexane		
ethanol	oil & grease standard		
ethylbenzene	pentane		
flourobenzene	Petroleum Ether		
Heptanes	pH buffer kit		
hexadecane	potassium hydroxide		
hexane	propylene glycol		
hydranal coulomat	silicon bath oil		
iso amyl alcohol	silver nitrate		
isobutyl alcohol	sulfolane		
Iso-octane	synthetic pump oil		
	eagents		
1,10-phenanthroline-p-toluene sulfonic acid salt	polyvinyl alcohol		
12-hydroxystearic acid	potassium bi-iodate		
2-chloro-6-(trichloromethyl)pyridine	potassium chloride solution		
4,5-dihydroxy-2,7-naphthalenedisulfonic acid, disodium salt	potassium dichromate		
4-aminoantipyine	potassium ferricyanide		
4-aminoantipyrine phosphate	potassium hydrogen phthalate		
acetic acid	potassium hydroxide		
acetonitrile	potassium iodide		
alkali iodine azide solution	potassium nitrate		
aminomethylpropanol	potassium nitrite		
Ammonium chloride	potassium oxalate		
Ammonium hydroxide	potassium permanganate		
Aniline	potassium phosphate, dibasic		
ascorbic acid	potassium phosphate, monobasic		
asino ethylpropanol	potassium pyrosulfate		

Chemical	ls in Lab Sump
Barium Chloride	potassium sodium tartrate
boric acid	potassium sulfate
Bromine	proprionic acid
Buffer solution pH10	SALT FOR DEICING AND WATER SOFTENERS
Buffer solution pH4	silica gel
Buffer solution pH7	silver chloride
cadmium	silver nitrate
calcium chloride	silver sulfate
calmagite	sodium acetate
Carbon Disulfide	sodium azide
CDTA trisodium salt	sodium bicarbonate
chloroform	sodium borate
chromium trioxide	sodium carbonate
citric acid	sodium chloride
Cupric Carbonate, basic	sodium gluconate
Cupric Nitrate	sodium hydrosulfite
dextrose	sodium hydroxide
diethanolamine hydrochloride	sodium iodide
DIETHYLENE GLYCOL MONOMETHYL ETHER (FSII)	sodium metabisulfite
dilute hydrochloric acid	sodium molybdate
Dilute Nitric Acid	sodium phosphate
dilute sulfuric acid	sodium Plumbite
diphenylcarbazone indicator	sodium sulfanilate
EDTA	sodium sulfate
ferrous ammonium sulfate	sodium sulfide
ferrous chloride	sodium sulfite
ferrous sulfate	sodium tartrate
formaldehyde	sodium thiosulfate
gentisic acid	Stadis 450
Glutamic Acid	starch indicator
glycerine	sulfanilic acid
hydrogen peroxide	sulfur
iodine	talc
iodine monochloride	tartaric acid
lithium chloride	trichoro-triflouro ethane
lithium hydroxide	various mineral salts
lithium nitrate	t-amyl alcohol
magnesium sulfate	tetrahydronaphthalene
Manganese Nitrate	tetramethylbenzenes
mercuric iodide	Toluene
Mercuric Nitrate	Toluene-d8
mercuric sulfate	trichloroethylene (slight possible)


Chemicals	in Lab Sump
METHYL CARBITOL SOLVENT (FSII)	trimethylbenzenes
naphtholbenzein	vacuum pump oil
phenol	Viscosity bath oil
phenolphthalein	water standard
phosphate buffer solution	xylenes
phosphoric acid	* (30-60% methanol,10-20% 1-pentanol, 5-15% imadazole, 5-25%
	dodecyldimethylamine)
	bon Samples
ARC	HVY Kero
Asphalt	Incoming Crude
ASPHALT DEFOAMER	JP-4
BRT bottoms	JP-8
BRT feed	Kero raffinate
BRT ovhd	Kero recycle
Combined Return crude	LAGO
cooling kero	LSR
COREXIT 307 CORROSION INHIBITOR	LT Kero
CU1 stabilizer	LUBRIZOL 8195 GASOLINE ADDITIVE
Deprop bottoms	MDEA
Deprop feed	MONOETHANOL AMINE (MEA)
Desalted Crude	MORLIFE 5000 ASPHALT ADDITIVE
ETHYL ANTIOXIDANT 733 MDA 80	N Kero
ETHYL ANTIOXIDANT 733 PDA (D) 25	Naphtha
F-76	Naphtha raffinate
FHR Return Crude	Naphtha recycle
Full Kero	propylene glycol
Gasoline (unleaded)	S Kero,
HAGO	sulfolane
HITECH 6423 FUEL ADDITIVE	VGO
HITECH 6531 FUEL ADDITIVE	
Waters - sa	mples & other
Desalter Water	Effluent wastewater
Crude OVHD water	Influent wastewater
C1 Stabilizer ovhd water	Gravel pit water
Deprop ovhd water	Gallery Pond water
Vacuum ovhd water	Fire water
BRT ovhd water	Cooling water for Octane Engines
Recovery ovhd water	Ice machine water
Benzene stripper	HVAC condensate
Boiler water	Deionizer condensate
	Cooling water for Bomb Calorimeter

	Chemicals in Lab Sump	
Cooling water for boiler		
	NALCO Chemicals	
NALclean 8940	Nalco EC 5816A	
NALclean 8960	Nalco EC 5828A	
Nalco 5376	Nalco EC 5830A	
Nalco 5403	Nalco EC2043a	
Nalco 5541	Nalco EC5345A	
Nalco 5541	Nalco EC5370A	
Nalco 5602	Nalco EC5407A	
Nalco 7320	Nalco SO771 indicator	
Nalco 8735	Nalco SO771 N-2 Titrant	
Nalco EC 5419A	Nalco SO780MQT-1	
	Detergents & cleaners	
409	Janitorial chemicals	
A-33 Dry respirator cleaner	Joy	
alcojet	neodisher A8	
alcotabs	neodisher EM	
citrus degreaser	neodisher N	
Clorox	neodisher Z	
Contrad 70	RBS solution	
ntrex Windex		



NEW LAB FLOOR PLAN

mance: 44 = 1'.	O" AFPROVED BY:	PRAWN BY NUMLET
DATS.	7	REVISED



BOILER PIPING SCHEMATIC

And it there talk the in the

EQUIPMENT SCHEDULE

SYMBOL	ITEM	CAPACITY/SIZE	HP	ELEC.	MANUFACTURER & MODEL	REMARKS
p- !	BOILER	664 HIBH GROSS CUTIFUT, B.S. GIPH FIRENCE ON NO. 2 FUEL CIL	Va	110/V603A	BURNHAM MODEL V-506	
A6-1	AIR SEFARATOR	2-V2*			TACO MODEL 438	
ET-I	EXPANSION TANK	31 GALLON VOLUME, 10 GALLON			ANTROL MODEL 6X-40Y EXTROL	TO & PAG
CAP-1	CIRCLATING PUMP	40 GFT1 & IS FT, TDH	ut V3	18/1407.2	GRUNDFOS MODEL UNG BIO-BIO, RUN ON BIPD.	\$
CPP-3	CIRCLEATING FUTT	48 (MPM & 16 FT, TOH	v /2	18/1407.2	GRUNDROS HODEL UMC BØ-80	
 	GLYCOL HAKE-UP	600 GPH 6 20 PBIG	V /3	1100007.2	GOULDS HODEL JOSHIS AGUA-AIR	
UH-1	UNIT HEATER	455 MBH, 180 = EUT, 20 = TETTE. DROP, 45 GPM, 0.15 FT. UPD	W 1/8	IBNO 3A	DUNHAM BUSH MODEL H300C	
PTPC-1	FINNED TUBE RADIATION	1000 BTUHVLF @ 100 AUT	-···		DURHAY BUSH HODEL SAIZ WITH 18H4×4-48 ELEMENT	
AHU-I	AIR HANDLER	23-45 CRM # 1.8" SP	7 2	7.5	MOCILAY MODEL CAMPOSPICAC WITH PLAT PILTERS, MIXING BOX, HTG AND CLG COIL, INTERNALLY ISOLATED	
HC-1	HEATING COIL	2345 CR1, \$ 40 65 WITH 214 GR11, 1860* EUIT, 20 *TENT DROP, 6.18" APD, 2.1 FT, WED	•		MODILAY MODEL SUHIDERS, LOCATED IN	
CC-!	COOLING COIL	1948 CPT, NO/61 US EAT, BS *		****	MODILAY MODEL SENDOWAR, LOCATED IN	***************************************
PHC-I	PREHEAT COIL	2340 CPT, -60+ TO P+ WITH 113 GPT, 100+ BUT, 30+ TEXTE DROP 0.00* APD, 0.11 FT, WPD			HALKLAY MODEL BUODEDH, SIZE 30x24	
cu-l	CONDENSING UNIT	1.5 TONS COOLING	27.7 AMP	200/3/60	YORK MODEL HIDBOTH	
∀ #-1	VENTILATING FAN	1000 CR1 4 0.25" 5P	1/8	115/1/60	PEN PAT PROPELLER FAN WITH MOTORIZED DATPER WALL SLEEVE, REAR GUARD	American April 1 american
L-I	LOUVER	SIZE AS INDICATED ON PLANS			MUSKIN MODEL BLF375D	
B D-1	BARCHETRIC DAMPER	SIZE AS INDICATED ON PLANS	# - ~ ~		RUSKIN MODEL BOG WITH STATIC PRESSURE	
CV-I	PHC-I CONTROL VALVE	2 WAY VALVE, CV#	'	P*****		†
CV-3	HC-I CONTROL VALVE	2-MAY VALVE CY=10				

SEQUENCE OF OPERATION


- BOILER B-I SHALL OPERATE IN ACCORDANCE LITH ITS PACKAGED CONTROL 6YSTEH, THE BOILERS SHALL RAIN IN A LEAD-LAS MODE, WITH THE SECOND BOILER OPERATING WEBSIVEN THE PRES BOILER IS NOT ABLE TO HAINTAIN WATER TEMPERATURE, ALTENNATE LEAD-LAS FRING ON EACH START, TWO POSITION CONTROL VALVE ASSOCIATED WITH EACH BOILER SHALL CLORE WEN LAS BOILER IS NOT RENING.
- 2. CIRCULATING PUTP CPH SHALL PLIN WHENEVER THE OUTNOTE TEMPERATURE IS BELOW 60 DECREEN F.
- 3. CIRCLEATING PLATS CP-2 CONTROLS SMILLAR TO OP-1.
- A. AIR HANDLING WIT AND BHALL RIN CONTINUOUSLY, PRESEAT COLL CONTROL YALVE, CV-1, SHALL HOULLATE TO MARTAN LEAVING AIR TETPERATURE OF O DEGREES F. THE MIXING DATPERS SHALL HOULLATE TO MARTAN BUILDING STATIC PRESENCE OF SIST NOISE. IN ADDITION, LEATING COLL NOISE CONTROL VALVE CV-2 AND THE MIXING DATPERS SHALL HOULLATE IN SEGUENCE TO MARTAN ROOM AIR TETPERATURE, SET POINT TO DEGREES F. RELIEF DATPER SHALL HOULLATE OF THE BUILDING PRESSURE RISES ABOVE SOO INCIDE.
- CONDENSANS UNIT OUT CONTROL SYSTEM SHALL BE ACTIVATED WHENEVER THE OUTSIDE AIM TETMERATURE IS ABOVE 56 DEGREES.
- . EXHAUST HOOD SHALL RUN FROM MANUAL BUITCH LOCATED ADJACENT TO HOOD.
- PLIPP PHI BHALL RUN TO MAINTAIN HYDRICHIC SYSTEM PRESSURE AS DETERMINED BY PLIPP PRESSURE SUITCH.
- PINED TUBE RADIATION ZONE VALVE SHALL CYCLE OPEN ON CALL FOR HEAT AS DETERTINED BY ROOM THEIRMOSTAT.
- Unit HEATER UH! FAN GHALL RUN ON A CALL FOR HEAT FROM THE ROOM THERMOSTAT, BET POINT 16 DEGREES, CONTINUOUS HUILD FLOU THROUGH UNIT HEATER.
- IS. VENTILATION FAN YFH SHALL RUN AND DAITMER SHALL OPEN ON CALL FOR COOLING FROM ROOM THERMOSTAT. SET POINT TO DEGREES.
- Il WHI IS CONTROLLISO FROM 1704 LINE THEMANDS THE NET IS COMMISCIPD OFF SAME THEREINS STATE FOR COUTHS MECHANSIAL MOONE


SPECIFICATIONS

- MANISH ALL BOWHTENT, MATERIAL AND LABOR TO PROVIDE COMPLETE AND OPERATING MECHANICAL SYSTEMS.
- ALL WORK TO BE DONE IN ACCORDANCE WITH LATEST EDITION OF UPC, UBC, UTC, ADEC, STACHA, ASHRAE AS APPLICABLE.
- 3. HEL ELECTRIC MOTORS AND STARTERS HAVE, BY U. 1.6 FED AND BEAR THE U. 1884... MOTOR: STARTERS SHIELD BE RIP 184ED BY THE MECHANICAL CONTRACTOR.
- 4. PERFORM AR AND WATER BALANCE ON VENTILATION AND HYDRICHIC SYSTEMS TO WITHWARD DESIGN CRITERIA AND PROVIDE A CORPLETE BALANCE REPORT FOR INSINEER'S REVIEW.
- B. DOMESTIC MASTE AND VENT PIPMS BELOU GRADE SHALL BE STANDARD MEIGHT HAB AND BYIGGT CAST MON PIPME WITH TYSEAU." JOINTS OR NO-HAB CAST MON PIPME WITH REOPINDE COLLAR AND STANDARD STEEL BAND, AND SHALL BE NOTALLED IN ACCORDANCE WITH IMPORTIN PLUMPSING CODE, ALL MASTE AND VENT PIPMS ABOVE GRADE SHALL BE TYPE DUV COPPER TUBNIS.
- ALL OLY MASTE PIPMS BELOW GRADE SHALL BE BLACK SCH. 46 PIPME WITH WELD PITTINGS AND WELDED JORTS IN ACCORDANCE WITH ADEC REGULARISMS. AND CHU-9023 SECTION IX, ASTE BOLLER AND PRESSURE VESSEL CODE. VEST PIPMS FOR OLY WINDER SYSTEM SHALL BE CAST RICK PIPM AND FITTINGS WITH NO-HID FITTINGS AND COUPLINGS. OLY MASTE SHALL BE WRAPTED WITH HEAT TAPE AND GABLODOGALLY PROTECTED.

 1. COPPER TURNIS FOR RELL OF PIPMS DELOW GRADE SHALL BE TYPE K' SOFT DRUM TURNIS HOR RELL PIPMS DELOW GRADE SHALL BE TYPE K' SOFT DRUM TURNIS WITH IL ARE PITTINGS OR WROT COPPER FITTINGS AND 10000 F SILVER SOLDER JONTS.
- COPPER TUBING FOR DOTIEGIC WATER STSTETS SHALL BE TITPE "L" HARD DRAWN TUBING WITH WROT COPPER FITTINGS AND 58-8 SOLDER JONTS.
- HEATING PIPING BHALL BE TYPE 1." HARD DRAWN COMPER WITH WROT COMPER FITTINGS AND 16-5 SOLDER JOHNS.
- ID. INSULATE HOT AND COLD DOTESTIC WATER LINES AND HEATING WATER LINES WITH IT THICK FIDERGLASS INSULATION WITH YAPOR BARRIER LACKET.
- II. NALLATE ALL OUTSIDE AIR NTAKE DICTS WITH 3" THICK, 3 LB. DENSITY RIGHD FROERGLAGS. NAULATE EXHAUST DUCTS WITH 1" THICK RIGHD FIRERGLAGS. ALL DUCT NOWLATION SHALL HAVE RIK JACKET.
- O. HYDRONIC HEATING BYBTEN SHALL BE PILLED WITH A BORN HOOLING OF PROPILE ME SOUTHERN SHITLED WITHOUT AND WITHOUT.
- 13. ALL DUCTUORK SHALL BE INSTALLED IN ACCORDINGE WITH SMACHA STANDARDS.
- H. EXHAUST LOUVERS SHALL BE SIZED TO PREVENT MOISTURE ENTRANMENT AND TO ALLOW NO MORE THAN 01" US PRESSURE DROP.
- TETPERATURE CONTROLS SHALL BE ELECTRICIBLECTRONIC AS REQUIRED TO PROVIDE A COMPLETE AND OPERABLE SYSTEM.
- 6. COORDINATE LOCATION AND HEIGHT OF ALL FINED TUBE RADIATION AND LOCATIONS OF ELECTRICAL WALL OUTLETS.

REVISIONS DATE	DESCRIPTION	l	**************************************
Service Of Albert		MAPCO REFINERY LABORATORY EXPANSION	
AOTH A	965		*AL
1 Ke 147 < 3	DATE 6/18/98		DE TENNE
A PERMIT	SCHEDULE	, SPECIFICATIONS, S	CHEMATIC
William Control	M-E-B EN	GINEERING SERVICES	M-1





BOALE:

APPROVED BY:

DAAWN BY


REVISED


PLUMBING LAYOUT


DRAWING NUMBER

1/8-3

INS PRINTED ON NO. WOODH CLEARPRI







Flint Hills Resources Alaska

NPR Laboratory Underground Piping Failure Evaluation

6/23/2010 Rev 0

7/21/10 Rev 1



Table of Contents

- I. Root cause analysis
- II. Leak rate estimation
- III. Chemical list
- IV. Leak test description
- V. Summary
- VI. Appendix A D-10-M1001 Lab piping drawing.
- VII. Appendix B Chemical compatibility for Neoprene
- VIII. Appendix C Drain pictures.
- IX. Appendix D Root Cause Map

Root Cause Analysis

A root cause analysis for the Flint Hills Resources Alaska (FHR), North Pole Refinery (NPR) laboratory drain piping was completed to determined the mechanism of failure on the lab sump drain piping. The root cause for the piping failure was found to be "Design not to Specification" on the drain piping connections at the time of installation in approximately 1985. This determination is based on a review of the original design information on the drain systems. The cast iron drain piping was put together during installation with No-hub style neoprene pipe couplings that are incompatible with certain hydrocarbons and can degrade when exposed to these hydrocarbons. See appendix A for building drain system drawings. See appendix B for chemical compatibility for Neoprene. Typical lab piping systems use Duriron high silicon cast iron piping and the appropriate couplings or glass piping systems manufactured by Corning or Kimax/Schott.


The piping drain systems were inspected by Keith Bradshaw from Fairbanks Pumping and Thawing on May 11, 2010. All of the piping drain systems are under the floor slab of the laboratory. Therefore, a flexiprobe P330 sewer camera was used to check the inside of the piping system. The flexiprobe camera was pushed inside of the piping system to the extent possible to inspect the piping internally for defects. The vertical sections of the piping was the only portion of the drain system which was clean enough to visually inspect with the camera. No-hub couplings in the area inspected were found to be deformed and in bad condition which would indicate leaking at the couplings inspected. See pictures in Appendix C.

II. Leak Rate Estimation

Objective: The objective of this section is to calculate the leak rate and the approximate leak orifice given the measured field data.

Background: A hydrostatic test using water was conducted on the under floor drain piping system at the NPR laboratory (lab) during the week of May 9th 2010. The underground drains were blinded and plugged at the outlet of the lab building. Water was used to fill the drain system liquid full. Air was removed by opening the cleanouts and observing the liquid level in all of the floor drains. When the water level reached the top of the floor drains, a timed test was started to measure loss of level over a given period of time. It was observed that the water level in the piping system dropped at a rate of 1 inch per hour. Measurements were taken with a tape measure at the top of the drain to the water level. Marks were made at the water levels with a paint pen to confirm the measurements.

Leak Rate Calculation



Given Burnoulli's equation for a small tank the combined equivalent leak orifice can be calculated.

$$\rho gz_{surface} + p_{atm} = \frac{1}{2} \rho V_{jet}^2 + \rho gz_{spout} + p_{atm}$$

$$V_{jet} = \sqrt{2g(z_{surface} - z_{spout})} = \sqrt{2g\Delta z}$$

$$Q = A_{jet}V_{jet} = CA_{spout}V_{jet}$$
[1],[2]

P = pressure V = velocity A = area of orifice C=nozzle constant p=density g=gravitational constant

Assumptions:

- 1) Pressure inside the drain pipe is the same as outside the drain pipe.
- 2) The piping system can be calculated as a small tank system
- 3) Orifice constant 0.9
- 4) Leaked fluid has low viscosity and is incompressible.

LEAK RATE CALCULATION

DRAINS	4	2	1.5	INCHES
TOTAL DRAINS	12	19	2	
DRAIN AREA	12.56637	3.141593	1.767146	INCHES^2
DRAIN HEIGHT	1	1	1	INCH
DRAIN VOLUME	12.56637	3.141593	1.767146	INCHES^3
TOAL DRAIN VOLUME	150.7964	59.69026	3.534292	INCHES^3
SUM OF DRAIN				*
VOLUME	214.021	INCHES^3		
GALLONS	0.926711	GALLONS		
TEST DURATION	60	MINUTES		
LEAK RATE	0.015445	GALLONS P	ER MINUTE	


ORIFICE CALCULATION

0.9 CONSTANT K
1 FT H2O
0.000686 INCH SQ ORIFICE AREA
0.029564 INCH ORIFICE DIAMETER


References

- 1) Cameron Hydraulic Data, C.C. Heald Nineteenth Edition
- 2) www.efunda.com/formulae/fluids/draining_tank.cfm#calc


Calculation Back Check



Inputs



Answers



III. Chemical List

IV. Leak test description

The under floor drain piping system was plugged at the outlet of the building. Water was then used to fill the piping. The cleanouts were opened to make sure all of the air was removed from the drains. The piping system was then filled to the top of the drains. All of the drains were observed to verify full of water prior to beginning the test. A timed test was then completed. The leak rate was determined to be 1 inch per hour based on water loss of a specific period of time.

V. Summary

A root cause analysis was completed. The root cause for the piping system failure was determined to be incorrect design specifications at the time of installation in approximately 1985. Drawings were found that indicated No-hub style connectors were originally installed. Fairbanks Pumping and Thawing was used to investigate the condition of the inside of the piping. A sewer camera was used to look down inside the piping system. The No-hub connectors were found to be in poor condition. Naphtha and toluene are on the list of chemicals disposed of down the drain system and would have been disposed since installation first occurred. These chemicals are known to be aggressive toward neoprene. Leak rate calculations were completed. The approximate leak rate was found to be in the order of 0.015 gallons per minute or 21.6 gallons per day assuming liquid full for 24 hours. This leak rate is for a 100% full drain piping system and therefore is highly conservative. During normal operations the drain piping system would be intermittently used, would be open channel flow and not liquid full. The leak rate during normal use is affected by many variables like amount of time utilized and volume placed into the system so it cannot be calculated with any degree of accuracy. FHR has discontinued use and abandoned the lab drain piping system. A new temporary above ground steel piping system has been installed and is being added to the above ground piping inspection program. A long term project will be designed and installed at a later date. Appendix A Lab piping drawings.

Appendix B Chemical compatibility for Neoprene

Chemical Compatibility Results Revise original search

Compatibility Level Selected D-Severe Effect

The chemicals which match your search results are listed below:

Chemical	Compatibility
Acetate Solvent	D-Severe Effect
Acetic Acid, Glacial	D-Severe Effect
Acetyl Chloride (dry)	D-Severe Effect
Alcohols:Diacetone	D-Severe Effect
Ammonium Bifluoride	D-Severe Effect
Amyl Acetate	D-Severe Effect
Amyl Chloride	D-Severe Effect

<u>Aniline</u>	D-Severe Effect
Aniline Hydrochloride	D-Severe Effect
Aqua Regia (80% HCl, 20% HNO3)	D-Severe Effect
Arochlor 1248	D-Severe Effect
Aromatic Hydrocarbons	D-Severe Effect
Asphalt	D-Severe Effect
<u>Benzaldehyde</u>	D-Severe Effect
Benzene	D-Severe Effect
Benzol	D-Severe Effect
Benzyl Chloride	D-Severe Effect
Bleaching Liquors	D-Severe Effect
Boric Acid	D-Severe Effect
<u>Bromine</u>	D-Severe Effect
Buttermilk	D-Severe Effect

Butyl Amine	D-Severe Effect
Butyl Ether	D-Severe Effect
Butyl Phthalate	D-Severe Effect
Butylacetate	D-Severe Effect
<u>Butylene</u>	D-Severe Effect
Butyric Acid	D-Severe Effect
Calcium Hypochlorite	D-Severe Effect
Carbolic Acid (Phenol)	D-Severe Effect
<u>Carbon Bisulfide</u>	D-Severe Effect
Carbon Disulfide	D-Severe Effect
Carbon Tetrachloride	D-Severe Effect
Carbon Tetrachloride (dry)	D-Severe Effect
Carbon Tetrachloride (wet)	D-Severe Effect
Carbonic Acid	D-Severe Effect

<u>Chlorinated Glue</u>	D-Severe Effect
Chlorine Water	D-Severe Effect
Chlorine, Anhydrous Liquid	D-Severe Effect
Chloroacetic Acid	D-Severe Effect
Chlorobenzene (Mono)	D-Severe Effect
<u>Chlorobromomethane</u>	D-Severe Effect
Chloroform	D-Severe Effect
Chlorosulfonic Acid	D-Severe Effect
Chromic Acid 10%	D-Severe Effect
Chromic Acid 30%	D-Severe Effect
Chromic Acid 5%	D-Severe Effect
Chromic Acid 50%	D-Severe Effect
Citric Oils	D-Severe Effect
<u>Cream</u>	D-Severe Effect

Cresols	D-Severe Effect		
Cresylic Acid	D-Severe Effect		
<u>Cyclohexane</u>	D-Severe Effect		
<u>Cyclohexanone</u>	D-Severe Effect		
<u>Diacetone Alcohol</u>	D-Severe Effect		
<u>Dichlorobenzene</u>	D-Severe Effect		
<u>Dichloroethane</u>	D-Severe Effect		
<u>Diethyl Ether</u>	D-Severe Effect		
<u>Dimethyl Aniline</u>	D-Severe Effect		
Dimethyl Formamide	D-Severe Effect		
<u>Diphenyl Oxide</u>	D-Severe Effect		
Ether	D-Severe Effect		
Ethyl Acetate	D-Severe Effect		
Ethyl Benzoate	D-Severe Effect		

Ethyl Ether	D-Severe Effect
Ethylene Chloride	D-Severe Effect
Ethylene Dichloride	D-Severe Effect
Ethylene Oxide	D-Severe Effect
Freonr 11	D-Severe Effect
<u>Furan Resin</u>	D-Severe Effect
<u>Furfural</u>	D-Severe Effect
Grape Juice	D-Severe Effect
Grease	D-Severe Effect
Hydrobromic Acid 100%	D-Severe Effect
Hydrobromic Acid 20%	D-Severe Effect
Hydrochloric Acid 100%	D-Severe Effect
Hydrofluoric Acid 100%	D-Severe Effect
<u>Hydrofluoric Acid 50%</u>	D-Severe Effect

Hydrofluoric Acid 75%	D-Severe Effect
Hydrogen Peroxide 10%	D-Severe Effect
Hydrogen Peroxide 100%	D-Severe Effect
Hydrogen Peroxide 30%	D-Severe Effect
Hydrogen Peroxide 50%	D-Severe Effect
<u>lodine</u>	D-Severe Effect
Isopropyl Acetate	D-Severe Effect
Isopropyl Ether	D-Severe Effect
<u>Isotane</u>	D-Severe Effect
Jet Fuel (JP3, JP4, JP5)	D-Severe Effect
<u>Ketones</u>	D-Severe Effect
<u>Lacquer Thinners</u>	D-Severe Effect
<u>Lacquers</u>	D-Severe Effect
Lard	D-Severe Effect

Lubricants	D-Severe Effect			
Maleic Acid	D-Severe Effect			
Maleic Anhydride	D-Severe Effect			
Malic Acid	D-Severe Effect			
<u>Melamine</u>	D-Severe Effect			
Methyl Acetone	D-Severe Effect			
Methyl Bromide	D-Severe Effect			
Methyl Butyl Ketone	D-Severe Effect			
Methyl Chloride	D-Severe Effect			
Methyl Ethyl Ketone	D-Severe Effect			
Methyl Ethyl Ketone Peroxide	D-Severe Effect			
Methyl Isobutyl Ketone	D-Severe Effect			
Methyl Isopropyl Ketone	D-Severe Effect			
Methyl Methacrylate	D-Severe Effect			

<u>Monoethanolamine</u>	D-Severe Effect		
<u>Morpholine</u>	D-Severe Effect		
Naphth <u>a</u>	D-Severe Effect		
Naphthalene	D-Severe Effect		
Nitric Acid (20%)	D-Severe Effect		
Nitric Acid (50%)	D-Severe Effect		
Nitric Acid (Concentrated)	D-Severe Effect		
<u>Nitrobenzene</u>	D-Severe Effect		
Nitromethane	D-Severe Effect		
Nitrous Acid	D-Severe Effect		
<u>Oils:Aniline</u>	D-Severe Effect		
Oils:Anise	D-Severe Effect		
Oils:Bay	D-Severe Effect		
Oils:Bone	D-Severe Effect		

Oils:Citric	D-Severe Effect		
Oils:Fuel (1, 2, 3, 5A, 5B, 6)	D-Severe Effect		
Oils:Lemon	D-Severe Effect		
Oils:Linseed	D-Severe Effect		
<u>Oils:Palm</u>	D-Severe Effect		
Oils:Peppermint	D-Severe Effect		
Oils:Pine	D-Severe Effect		
Oils:Sesame Seed	D-Severe Effect		
Oils:Silicone	D-Severe Effect		
Oils:Sperm (whale)	D-Severe Effect		
Oils:Tanning	D-Severe Effect		
Oils:Turbine	D-Severe Effect		
<u>Oleum 100%</u>	D-Severe Effect		
Oleum 25%	D-Severe Effect		

Oxalic Acid (cold)	D-Severe Effect
Palmitic Acid	D-Severe Effect
Perchloroethylene	D-Severe Effect
Phenol (10%)	D-Severe Effect
Phenol (Carbolic Acid)	D-Severe Effect
Phosphoric Acid (crude)	D-Severe Effect
Phosphorus Trichloride	D-Severe Effect
Plating Solutions, Chromium Plating: Barrel Chrome Bath 95°F	D-Severe Effect
Plating Solutions, Chromium Plating: Black Chrome Bath 115°F	D-Severe Effect
Plating Solutions, Chromium Plating: Chromic-Sulfuric Bath 130°F	D-Severe Effect
Plating Solutions, Chromium Plating: Fluoride Bath 130°F	D-Severe Effect
Plating Solutions, Chromium Plating: Fluosilicate Bath 95°F	D-Severe Effect
Plating Solutions, Copper Plating (Misc): Copper (Electroless)	D-Severe Effect
Plating Solutions, Iron Plating: Ferrous Chloride Bath 190°F	D-Severe Effect

Plating Solutions, Nickel Plating: Electroless 200°F	D-Severe Effect
<u>Propylene</u>	D-Severe Effect
<u>Pyridine</u>	D-Severe Effect
Resorcinal	D-Severe Effect
Shellac (Orange)	D-Severe Effect
<u>Styrene</u>	D-Severe Effect
Sulfur Chloride	D-Severe Effect
Sulfur Dioxide (dry)	D-Severe Effect
Sulfur Trioxide	D-Severe Effect
Sulfur Trioxide (dry)	D-Severe Effect
Sulfuric Acid (75-100%)	D-Severe Effect
Sulfuric Acid (cold concentrated)	D-Severe Effect
Sulfuric Acid (hot concentrated)	D-Severe Effect
Tetrachloroethane	D-Severe Effect

Tetrachloroethylene	D-Severe Effect		
Tetrahydrofuran	D-Severe Effect		
Toluene (Toluol)	D-Severe Effect		
Trichloroacetic Acid	D-Severe Effect		
Trichloroethane	D-Severe Effect		
<u>Trichloroethylene</u>	D-Severe Effect		
<u>Turpentine</u>	D-Severe Effect		
<u>Urine</u>	D-Severe Effect		
<u>Varnish</u>	D-Severe Effect		
Vinyl Acetate	D-Severe Effect		
Vinyl Chloride	D-Severe Effect		
Xylene	D-Severe Effect		

Explanation of Footnotes

- 1. Satisfactory to 72°F (22°C)
- 2. Satisfactory to 120°F (48° C)

Ratings -- Chemical Effect

A = Excellent.

B = Good -- Minor Effect, slight corrosion or discoloration.

C = Fair -- Moderate Effect, not recommended for continuous use. Softening, loss of strength, swelling may occur.


D = Severe Effect, not recommended for **ANY** use.

N/A = Information Not Available.


Appendix C Drain pictures.




Picture 1. flexiprobe P330 used to view inside piping drain system.



Picture 2. Floor drain with deformed neoprene NO-HUB connector



Picture 3. Floor drain clean-out with neoprene NO-HUB connector



	¥		